

# Scope of works

To replace all mall doors which lead to back of house areas.



## Shopping Centre

### Mall Doors

**LOCATION: Southampton**

**CLIENT: Workman**

## Overview

After nearly 20 years of use it was decided that the laminated doors which separated the mall space of a Shopping Centre from the back of house could no longer be repaired and a durable and functional replacement was required.

We found a supplier who could provide post formed, 3mm plastic encapsulated door sets which would be in keeping with the existing maple finish and who could provide all the necessary certifications required for the fire doors.

We worked with the client to identify heavily trafficked routes and selected specific door sets which would be equipped with automatic opening mechanisms in order to further improve the longevity of the doors.

The Client was considering installing bio metric locks on these door sets at some time in the future and so we worked with the incumbent data network provider to ensure that cables were run back to the correct data cabs and within the door frames.

We designed and installed signage to specific door sets in keeping with the clients branding to identify routes to back of house areas where dry risers were cited.

We ensured that works created limited disruption to the fire integrity of the Shopping Centre and works were completed outside of normal working hours.